

HOM. AREA	DESCRIPTION	SAMPLE DATE	ASBESTOS (Y/N/A)			FRIABLE	2022	RESPONSE	SPECIAL	TYPE	RECOMMENDATIONS
				DAM	QUANTITY		ASSESSMENT	ACTION	CLEANING	OF	
							40 CFR 763.88	START/END DATES	NEEDED	DAMAGE	REFER TO REPORT FOR DATES AND COST ESTIMATES
1	SOFT CEILING PLASTER										
	MAIN HALLWAY	7/7/2010	Y	N	1,000 SF	NF	5		N		GOOD CONDITION - O&M
2	GREY 12" X 12" VINYL FLOOR TILE										
	STAGE	7/7/2010	Y	N	715 SF	NF	5		N		GOOD CONDITION - O&M
3	MASTIC FOR GREY 12" X 12" VINYL FLOOR TILE										
	STAGE	7/7/2010	Y	N	715 SF	NF	5		N		GOOD CONDITION - O&M
4	TAN/RED 12" X 12" VINYL FLOOR TILE										
	ROOM 10		A	N	940 SF	NF	5		N		GOOD CONDITION - O&M
	ART ROM 16			N	820 SF	NF	5		N		GOOD CONDITION - O&M
5	MASTIC FOR TAN/RED 12" X 12" VINYL FLOOR TILE										
	ROOM 10		A	N	940 SF	NF	5		N		GOOD CONDITION - O&M
	ART ROM 16			N	820 SF	NF	5		N		GOOD CONDITION - O&M
6	GREY 9" X 9" VINYL FLOOR TILE										
	ROOM 13 UNDER OTHER FLOORING		A	N	900 SF	NF	5		N		GOOD CONDITION - O&M
	ROOM 12 UNDER OTHER FLOORING			N	940 SF	NF	5		N		GOOD CONDITION - O&M
	ROOM 11 UNDER OTHER FLOORING			N	900 SF	NF	5		N		GOOD CONDITION - O&M
	ROOM 9 UNDER OTHER FLOORING			N	900 SF	NF	5		N		GOOD CONDITION - O&M
	ROOM 8 UNDER OTHER FLOORING			N	940 SF	NF	5		N		GOOD CONDITION - O&M
	ROOM 6			N	940 SF	NF	5		N		GOOD CONDITION - O&M
	ROOM 5 UNDER OTHER FLOORING			N	900 SF	NF	5		N		GOOD CONDITION - O&M
	ROOM 2			N	940 SF	NF	5		N		GOOD CONDITION - O&M
	ROOM 7 UNDER OTHER FLOORING			N	900 SF	NF	5		N		GOOD CONDITION - O&M
	CLOSET BY VAULT			N	15 SF	NF	5		N		GOOD CONDITION - O&M

ASBESTOS TYPE
CHRY Chrysotile
AMOS Amosite
ACTI Actinolite
ANTH Anthophyllite
CROC Crocidolite
NA/PS Not Analyzed/Positive Stop

QUANTITY
SF Square Feet
LF Linear Feet
EA Each
TO Total

TYPE OF MATERIAL
M Miscellaneous
S Surfacing
T Thermal

ASBESTOS
Y Yes
N No
A Assumed

NOTES
HV - HEPA VACCUUM
2X/WK - TWICE PER WEEK
1X/WK - ONCE PER WEEK
L - LOOSE
DE - DETERRIORATED
D - DAMAGED
SD - SIGNIFICANT DAMAGE

- (1) Damaged or significantly damaged thermal system insulation ACM.
(2) Damaged friable surfacing ACM.
(3) Significantly damaged friable surfacing ACM.
(4) Damaged or significantly damaged friable miscellaneous ACM.
(5) ACBM with potential for damage.
(6) ACBM with potential for significant damage.
(7) Any remaining friable ACBM or friable suspected ACBM.

HOM. AREA	DESCRIPTION	SAMPLE DATE	ASBESTOS (Y/N/A)			FRIABLE	2022	RESPONSE	SPECIAL	TYPE	RECOMMENDATIONS
				DAM	QUANTITY		ASSESSMENT	ACTION	CLEANING	OF	
							40 CFR 763.88	START/END DATES	NEEDED	DAMAGE	REFER TO REPORT FOR DATES AND COST ESTIMATES
7	MASTIC FOR GREY 9" X 9" VINYL FLOOR TILE										
	ROOM 13 UNDER OTHER FLOORING		A	N	900 SF	NF	5		N		GOOD CONDITION - O&M
	ROOM 12 UNDER OTHER FLOORING			N	940 SF	NF	5		N		GOOD CONDITION - O&M
	ROOM 11 UNDER OTHER FLOORING			N	900 SF	NF	5		N		GOOD CONDITION - O&M
	ROOM 9 UNDER OTHER FLOORING			N	900 SF	NF	5		N		GOOD CONDITION - O&M
	ROOM 8 UNDER OTHER FLOORING			N	940 SF	NF	5		N		GOOD CONDITION - O&M
	ROOM 6			N	940 SF	NF	5		N		GOOD CONDITION - O&M
	ROOM 5 UNDER OTHER FLOORING			N	900 SF	NF	5		N		GOOD CONDITION - O&M
	ROOM 2			N	940 SF	NF	5		N		GOOD CONDITION - O&M
	ROOM 7 UNDER OTHER FLOORING			N	900 SF	NF	5		N		GOOD CONDITION - O&M
	CLOSET BY VAULT			N	15 SF	NF	5		N		GOOD CONDITION - O&M
8	VARIOUS COLORS OF 12" X 12" VINYL FLOOR TILE										
	ROOM 13 OVER 9" X 9" VINYL FLOOR TILE		A	N	900 SF	NF	5		N		GOOD CONDITION - O&M
	ROOM 12 OVER 9" X 9" VINYL FLOOR TILE			N	940 SF	NF	5		N		GOOD CONDITION - O&M
	ROOM 11 OVER 9" X 9" VINYL FLOOR TILE			N	900 SF	NF	5		N		GOOD CONDITION - O&M
	ROOM 9 OVER 9" X 9" VINYL FLOOR TILE			N	900 SF	NF	5		N		GOOD CONDITION - O&M
	ROOM 8 OVER 9" X 9" VINYL FLOOR TILE			N	940 SF	NF	5		N		GOOD CONDITION - O&M
	ROOM 6			N	940 SF	NF	5		N		GOOD CONDITION - O&M
	ROOM 5 OVER 9" X 9" VINYL FLOOR TILE			N	900 SF	NF	5		N		GOOD CONDITION - O&M
	ROOM 2			N	940 SF	NF	5		N		GOOD CONDITION - O&M
	ROOM 7 OVER 9" X 9" VINYL FLOOR TILE			N	900 SF	NF	5		N		GOOD CONDITION - O&M
CLOSET BY VAULT			N	15 SF	NF	5		N		GOOD CONDITION - O&M	
9	TRANSITE GREEN BOARD										
	ROOM 17		A	N	1 EA	NF	5		N		GOOD CONDITION - O&M
	ROOM 15			N	1 EA	NF	5		N		GOOD CONDITION - O&M
10	PIPE AND HARD JOINT INSULATION										
	TRENCH	7/7/2010	Y	N							CONDITION UNKNOWN- O&M
	STAIRS TO BOILER ROOM			N	18 LF	NF	5		N		GOOD CONDITION - O&M
	CAFETERIA STORAGE ROOM			N	25 LF	NF	5		N		GOOD CONDITION - O&M

ASBESTOS TYPE
CHRY Chrysotile
AMOS Amosite
ACTI Actinolite
ANTH Anthophyllite
CROC Crocidolite
NA/PS Not Analyzed/Positive Stop

QUANTITY
SF Square Feet
LF Linear Feet
EA Each
TO Total

TYPE OF MATERIAL
M Miscellaneous
S Surfacing
T Thermal

ASBESTOS
Y Yes
N No
A Assumed

NOTES
HV - HEPA VACCUUM
2X/WK - TWICE PER WEEK
1X/WK - ONCE PER WEEK
L - LOOSE
DE - DETERRIORATED
D - DAMAGED
SD - SIGNIFICANT DAMAGE

- (1) Damaged or significantly damaged thermal system insulation ACM.
(2) Damaged friable surfacing ACM.
(3) Significantly damaged friable surfacing ACM.
(4) Damaged or significantly damaged friable miscellaneous ACM.
(5) ACBM with potential for damage.
(6) ACBM with potential for significant damage.
(7) Any remaining friable ACBM or friable suspected ACBM.

HOM. AREA	DESCRIPTION	SAMPLE DATE	ASBESTOS (Y/N/A)			FRIABLE	2022	RESPONSE	SPECIAL	TYPE	RECOMMENDATIONS
				DAM	QUANTITY		ASSESSMENT	ACTION	CLEANING	OF	
							40 CFR 763.88	START/END DATES	NEEDED	DAMAGE	REFER TO REPORT FOR DATES AND COST ESTIMATES
11	GLUE FOR VARIOUS COLORS OF 12" X 12" VINYL FLOOR TILE										
	ROOM 13 OVER 9" X 9" VINYL FLOOR TILE		A	N	900 SF	NF	5		N		GOOD CONDITION - O&M
	ROOM 12 OVER 9" X 9" VINYL FLOOR TILE			N	940 SF	NF	5		N		GOOD CONDITION - O&M
	ROOM 11 OVER 9" X 9" VINYL FLOOR TILE			N	900 SF	NF	5		N		GOOD CONDITION - O&M
	ROOM 9 OVER 9" X 9" VINYL FLOOR TILE			N	900 SF	NF	5		N		GOOD CONDITION - O&M
	ROOM 8 OVER 9" X 9" VINYL FLOOR TILE			N	940 SF	NF	5		N		GOOD CONDITION - O&M
	ROOM 6			N	940 SF	NF	5		N		GOOD CONDITION - O&M
	ROOM 5 OVER 9" X 9" VINYL FLOOR TILE			N	900 SF	NF	5		N		GOOD CONDITION - O&M
	ROOM 2			N	940 SF	NF	5		N		GOOD CONDITION - O&M
	ROOM 7 OVER 9" X 9" VINYL FLOOR TILE			N	900 SF	NF	5		N		GOOD CONDITION - O&M
	CLOSET BY VAULT			N	15 SF	NF	5		N		GOOD CONDITION - O&M
12	TRANSITE GREEN BOARD										
	ROOM 17		A	N	1 EA	NF	5		N		GOOD CONDITION - O&M
	ROOM 15			N	1 EA	NF	5		N		GOOD CONDITION - O&M
13	2' X 4' SUSPENDED ACOUSTICAL CEILING TILE										
	LOBBY	1/27/2020	N	N	625 SF						
	GYMNASIUM HALLWAY			N	1,000 SF						
	KINDERGARTEN			N	3,000 SF						
14	2' X 2' SUSPENDED ACOUSTICAL CEILING TILE										
	HALLWAY 8-13	1/27/2020	N	N	930 SF						
	HALLWAY 2-7			N	930 SF						
15	WHITE/GREY 12" X 12" VINYL FLOOR TILE										
	GYMNASIUM HALLWAY		A	N	1,000 SF	NF	5		N		GOOD CONDITION - O&M

ASBESTOS TYPE
CHRY Chrysotile
AMOS Amosite
ACTI Actinolite
ANTH Anthophyllite
CROC Crocidolite
NA/PS Not Analyzed/Positive Stop

QUANTITY
SF Square Feet
LF Linear Feet
EA Each
TO Total

TYPE OF MATERIAL
M Miscellaneous
S Surfacing
T Thermal

ASBESTOS
Y Yes
N No
A Assumed

NOTES
HV - HEPA VACCUUM
2X/WK - TWICE PER WEEK
1X/WK - ONCE PER WEEK
L - LOOSE
DE - DETERRIORATED
D - DAMAGED
SD - SIGNIFICANT DAMAGE

- (1) Damaged or significantly damaged thermal system insulation ACM.
- (2) Damaged friable surfacing ACM.
- (3) Significantly damaged friable surfacing ACM.
- (4) Damaged or significantly damaged friable miscellaneous ACM.
- (5) ACBM with potential for damage.
- (6) ACBM with potential for significant damage.
- (7) Any remaining friable ACBM or friable suspected ACBM.

HOM. AREA	DESCRIPTION	SAMPLE DATE	ASBESTOS (Y/N/A)			FRIABLE	2022	RESPONSE	SPECIAL	TYPE	RECOMMENDATIONS
				ASSESSMENT	ACTION		CLEANING	OF			
				40 CFR 763.88	START/END DATES		NEEDED	DAMAGE	REFER TO REPORT FOR DATES AND COST ESTIMATES		
16	MASTIC FOR WHITE/GREY 12" X 12" VINYL FLOOR TILE										
	GYMNASIUM HALLWAY		A	N	1,000 SF	NF	5		N		GOOD CONDITION - O&M
17	PINK 12" X 12" VINYL FLOOR TILE										
	MUSIC ROOM 14		A	N	820 SF	NF	5		N		GOOD CONDITION - O&M
18	MASTIC FOR PINK 12" X 12" VINYL FLOOR TIE										
	MUSIC ROOM 14		A	N	820 SF	NF	5		N		GOOD CONDITION - O&M
19	BLUE 12" X 12" VINYL FLOOR TILE										
	ROOM 17		A	N	820 SF	NF	5		N		GOOD CONDITION - O&M
	ROOM 3			N	820 SF	NF	5		N		GOOD CONDITION - O&M
20	MASTIC FOR BLUE 12" X 12" VINYL FLOOR TILE										
	ROOM 17		A	N	820 SF	NF	5		N		GOOD CONDITION - O&M
	ROOM 3			N	820 SF	NF	5		N		GOOD CONDITION - O&M
21	WHITE 12" X 12" VINYL FLOOR TILE										
	MAIN OFFICE		A	N	450 SF	NF	5		N		GOOD CONDITION - O&M
22	MASTIC FOR WHITE 12" X 12" VINYL FLOOR TILE										
	MAIN OFFICE		A	N	450 SF	NF	5		N		GOOD CONDITION - O&M

ASBESTOS TYPE
CHRY Chrysotile
AMOS Amosite
ACTI Actinolite
ANTH Anthophyllite
CROC Crocidolite
NA/PS Not Analyzed/Positive Stop

QUANTITY
SF Square Feet
LF Linear Feet
EA Each
TO Total

TYPE OF MATERIAL
M Miscellaneous
S Surfacing
T Thermal

ASBESTOS
Y Yes
N No
A Assumed

NOTES
HV - HEPA VACCUUM
2X/WK - TWICE PER WEEK
1X/WK - ONCE PER WEEK
L - LOOSE
DE - DETERRIORATED
D - DAMAGED
SD - SIGNIFICANT DAMAGE

- (1) Damaged or significantly damaged thermal system insulation ACM.
- (2) Damaged friable surfacing ACM.
- (3) Significantly damaged friable surfacing ACM.
- (4) Damaged or significantly damaged friable miscellaneous ACM.
- (5) ACBM with potential for damage.
- (6) ACBM with potential for significant damage.
- (7) Any remaining friable ACBM or friable suspected ACBM.

HOM. AREA	DESCRIPTION	SAMPLE DATE	ASBESTOS (Y/N/A)			FRIABLE	2022	RESPONSE	SPECIAL	TYPE	RECOMMENDATIONS
				DAM	QUANTITY		ASSESSMENT	ACTION	CLEANING	OF	
							40 CFR 763.88	START/END DATES	NEEDED	DAMAGE	REFER TO REPORT FOR DATES AND COST ESTIMATES
23	GREEN 12" X 12" VINYL FLOOR TILE										
	ROOM 15		A	N	820 SF	NF	5		N		GOOD CONDITION - O&M
	NURSE			N	350 SF	NF	5		N		GOOD CONDITION - O&M
24	MASTIC FOR GREEN 12" X 12" VINYL FLOOR TILE										
	ROOM 15		A	N	820 SF	NF	5		N		GOOD CONDITION - O&M
	NURSE			N	350 SF	NF	5		N		GOOD CONDITION - O&M
25	GREY/BLUE 12" X 12" VINYL FLOOR TIE										
	ROOM 19		A	N	1,330 SF	NF	5		N		GOOD CONDITION - O&M
	LIBRARY			N	150 SF	NF	5		N		GOOD CONDITION - O&M
	COMPUTER LAB			N	150 SF	NF	5		N		GOOD CONDITION - O&M
	HALLWAY BY CAFETERIA			N	300 SF	NF	5		N		GOOD CONDITION - O&M
	LAC ROOM 18			N	380 SF	NF	5		N		GOOD CONDITION - O&M
26	MASTIC FOR GREY/BLUE 12" X 12" VINYL FLOOR TIE										
	ROOM 19		A	N	1,330 SF	NF	5		N		GOOD CONDITION - O&M
	LIBRARY			N	150 SF	NF	5		N		GOOD CONDITION - O&M
	COMPUTER LAB			N	150 SF	NF	5		N		GOOD CONDITION - O&M
	HALLWAY BY CAFETERIA			N	300 SF	NF	5		N		GOOD CONDITION - O&M
	LAC ROOM 18			N	380 SF	NF	5		N		GOOD CONDITION - O&M
27	TEXTURED CEILING PLASTER										
	HALLWAY BY ROOM 6	7/7/2010	N	N	400 SF						
28	INTERIOR WINDOW CAULKING										
	GYMNASIUM HALLWAY		A	N	12 TO	NF	5		N		GOOD CONDITION - O&M
	HALLWAY 15/16			N	24 TO	NF	5		N		GOOD CONDITION - O&M
	HALLWAY 8-13			N	60 TO	NF	5		N		GOOD CONDITION - O&M
	HALLWAY 2-7			N	60 TO	NF	5		N		GOOD CONDITION - O&M
	MAIN HALLWAY			N	6 TO	NF	5		N		GOOD CONDITION - O&M

ASBESTOS TYPE
CHRY Chrysotile
AMOS Amosite
ACTI Actinolite
ANTH Anthophyllite
CROC Crocidolite
NA/PS Not Analyzed/Positive Stop

QUANTITY
SF Square Feet
LF Linear Feet
EA Each
TO Total

TYPE OF MATERIAL
M Miscellaneous
S Surfacing
T Thermal

ASBESTOS
Y Yes
N No
A Assumed

NOTES
HV - HEPA VACCUUM
2X/WK - TWICE PER WEEK
1X/WK - ONCE PER WEEK
L - LOOSE
DE - DETERRIORATED
D - DAMAGED
SD - SIGNIFICANT DAMAGE

- (1) Damaged or significantly damaged thermal system insulation ACM.
- (2) Damaged friable surfacing ACM.
- (3) Significantly damaged friable surfacing ACM.
- (4) Damaged or significantly damaged friable miscellaneous ACM.
- (5) ACBM with potential for damage.
- (6) ACBM with potential for significant damage.
- (7) Any remaining friable ACBM or friable suspected ACBM.

HOM. AREA	DESCRIPTION	SAMPLE DATE	ASBESTOS (Y/N/A)			FRIABLE	2022	RESPONSE	SPECIAL	TYPE	
				DAM	QUANTITY		ASSESSMENT 40 CFR 763.88	ACTION START/END DATES	CLEANING NEEDED	OF DAMAGE	RECOMMENDATIONS
											REFER TO REPORT FOR DATES AND COST ESTIMATES
29	LIGHT GREEN 12" X 12" VINYL FLOOR TILE										
	MAIN HALLWAY		A	N	800 SF	NF	5		N		GOOD CONDITION - O&M
	TEACHER'S ROOM			N	400 SF	NF	5		N		GOOD CONDITION - O&M
	CAFETERIA			N	2,400 SF	NF	5		N		GOOD CONDITION - O&M
30	MASTIC FOR LIGHT GREEN 12" X 12" VINYL FLOOR TILE										
	MAIN HALLWAY		A	N	800 SF	NF	5		N		GOOD CONDITION - O&M
	TEACHER'S ROOM			N	400 SF	NF	5		N		GOOD CONDITION - O&M
	CAFETERIA			N	2,400 SF	NF	5		N		GOOD CONDITION - O&M
31	BLACK SINK COATING										
	KINDERGARTEN 19/21/23		A	N	3 TO	NF	5		N		GOOD CONDITION - O&M
	ART ROOM 16			N	1 EA	NF	5		N		GOOD CONDITION - O&M
32	GREY SINK COATING										
	TEACHER'S ROOM		A	N	1 EA	NF	5		N		GOOD CONDITION - O&M
33	YELLOW SINK COATING										
	ROOM 17		A	N	1 EA	NF	5		N		GOOD CONDITION - O&M
	ROOM 15			N	1 EA	NF	5		N		GOOD CONDITION - O&M
34	SMOOTH CEILING/WALL PLASTER										
	KITCHEN	7/7/2010	N	N							
	FRONT OFFICE			N							
	MAIN HALLWAYS			N							
	STORAGE ROOMS			N							
	BATHROOMS			N							
			TOTAL	25,000 SF							

ASBESTOS TYPE
CHRY Chrysotile
AMOS Amosite
ACTI Actinolite
ANTH Anthophyllite
CROC Crocidolite
NA/PS Not Analyzed/Positive Stop

QUANTITY
SF Square Feet
LF Linear Feet
EA Each
TO Total

TYPE OF MATERIAL
M Miscellaneous
S Surfacing
T Thermal

ASBESTOS
Y Yes
N No
A Assumed

NOTES
HV - HEPA VACCUUM
2X/WK - TWICE PER WEEK
1X/WK - ONCE PER WEEK
L - LOOSE
DE - DETERRIORATED
D - DAMAGED
SD - SIGNIFICANT DAMAGE

- (1) Damaged or significantly damaged thermal system insulation ACM.
- (2) Damaged friable surfacing ACM.
- (3) Significantly damaged friable surfacing ACM.
- (4) Damaged or significantly damaged friable miscellaneous ACM.
- (5) ACBM with potential for damage.
- (6) ACBM with potential for significant damage.
- (7) Any remaining friable ACBM or friable suspected ACBM.

HOM. AREA	DESCRIPTION	SAMPLE DATE	ASBESTOS (Y/N/A)			FRIABLE	2022 ASSESSMENT 40 CFR 763.88	RESPONSE ACTION START/END DATES	SPECIAL CLEANING NEEDED	TYPE OF DAMAGE	RECOMMENDATIONS	
				DAM	QUANTITY							REFER TO REPORT FOR DATES AND COST ESTIMATES
35	LIGHT TAN 12" X 12" VINYL FLOOR TILE											
	CONFERENCE ROOM		A	N	160 SF	NF	5		N		GOOD CONDITION - O&M	
36	MASTIC FOR LIGHT TAN 12" X 12" VINYL FLOOR TILE											
	CONFERENCE ROOM		A	N	160 SF	NF	5		N		GOOD CONDITION - O&M	
37	WHITE/BLUE/PINK 12" X 12" VINYL FLOOR TILE											
	KINDERGARTEN ROOM 23		A	N	1,330 SF	NF	5		N		GOOD CONDITION - O&M	
	KINDERGARTEN ROOM 21			N	1,330 SF	NF	5		N		GOOD CONDITION - O&M	
38	MASTIC FOR WHITE/BLUE/PINK 12" X 12" VINYL FLOOR TILE											
	KINDERGARTEN ROOM 23		A	N	1,330 SF	NF	5		N		GOOD CONDITION - O&M	
	KINDERGARTEN ROOM 21			N	1,330 SF	NF	5		N		GOOD CONDITION - O&M	

ASBESTOS TYPE
CHRY Chrysotile
AMOS Amosite
ACTI Actinolite
ANTH Anthophyllite
CROC Crocidolite
NA/PS Not Analyzed/Positive Stop

QUANTITY
SF Square Feet
LF Linear Feet
EA Each
TO Total

TYPE OF MATERIAL
M Miscellaneous
S Surfacing
T Thermal

ASBESTOS
Y Yes
N No
A Assumed

NOTES
HV - HEPA VACCUUM
2X/WK - TWICE PER WEEK
1X/WK - ONCE PER WEEK
L - LOOSE
DE - DETERRIORATED
D - DAMAGED
SD - SIGNIFICANT DAMAGE

- (1) Damaged or significantly damaged thermal system insulation ACM.
- (2) Damaged friable surfacing ACM.
- (3) Significantly damaged friable surfacing ACM.
- (4) Damaged or significantly damaged friable miscellaneous ACM.
- (5) ACBM with potential for damage.
- (6) ACBM with potential for significant damage.
- (7) Any remaining friable ACBM or friable suspected ACBM.