

HOM. AREA	DESCRIPTION	SAMPLE DATE	ASBESTOS (Y/N/A)			FRIABLE	2022	RESPONSE	SPECIAL	TYPE	RECOMMENDATIONS
				DAM	QUANTITY		ASSESSMENT	ACTION	CLEANING	OF	REFER TO REPORT FOR DATES AND COST ESTIMATES
							40 CFR 763.88	START/END DATES	NEEDED	DAMAGE	
1	TRANSITE PANEL										
	ATTIC		A	N	1,415 SF	NF	5		N		GOOD CONDITION - O&M
2	PIPE AND HARD JOINT INSULATION										
	ATTIC		A	N	3,100 LF	NF	5		N		GOOD CONDITION - O&M
	BAEMENT GIRL'S LOCKER ROOM OFFICE			N	22 LF	NF	5		N		GOOD CONDITION - O&M
3	HARD JOINT INSULATION										
	BOILER ROOM		A	N	5 TO	NF	5		N		GOOD CONDITION - O&M
4	OFF WHITE 12" X 12" VINYL FLOOR TILE										
	ROOM 17	7/6/2010	Y	N	910 SF	NF	5		N		GOOD CONDITION - O&M
	ROOM 14			N	875 SF	NF	5		N		GOOD CONDITION - O&M
	ROOM 7			N	865 SF	NF	5		N		GOOD CONDITION - O&M
	ROOM 6			N	865 SF	NF	5		N		GOOD CONDITION - O&M
5	MASTIC FOR OFF WHITE 12" X 12" VINYL FLOOR TILE										
	ROOM 17	7/6/2010	Y	N	910 SF	NF	5		N		GOOD CONDITION - O&M
	ROOM 14			N	875 SF	NF	5		N		GOOD CONDITION - O&M
	ROOM 7			N	865 SF	NF	5		N		GOOD CONDITION - O&M
	ROOM 6			N	865 SF	NF	5		N		GOOD CONDITION - O&M
6	BLACK 12" X 12" VINYL FLOOR TILE										
	ROOM 14	7/7/2010	Y	N	55 SF	NF	5		N		GOOD CONDITION - O&M
	ROOM 13			N	55 SF	NF	5		N		GOOD CONDITION - O&M
	ROOM 12			N	55 SF	NF	5		N		GOOD CONDITION - O&M
	ROOM 10			N	55 SF	NF	5		N		GOOD CONDITION - O&M
	ROOM 5 UNDER OTHER FLOORING			N	55 SF	NF	5		N		GOOD CONDITION - O&M

ASBESTOS TYPE  
CHRY Chrysotile  
AMOS Amosite  
ACTI Actinolite  
ANTH Anthophyllite  
CROC Crocidolite  
NA/PS Not Analyzed/Positive Stop

QUANTITY  
SF Square Feet  
LF Linear Feet  
EA Each  
TO Total

TYPE OF MATERIAL  
M Miscellaneous  
S Surfacing  
T Thermal

ASBESTOS  
Y Yes  
N No  
A Assumed

NOTES  
HV - HEPA VACCUUM  
2X/WK - TWICE PER WEEK  
1X/WK - ONCE PER WEEK  
L - LOOSE  
DE - DETERRIORATED  
D - DAMAGED  
SD - SIGNIFICANT DAMAGE

- (1) Damaged or significantly damaged thermal system insulation ACM.  
(2) Damaged friable surfacing ACM.  
(3) Significantly damaged friable surfacing ACM.  
(4) Damaged or significantly damaged friable miscellaneous ACM.  
(5) ACBM with potential for damage.  
(6) ACBM with potential for significant damage.  
(7) Any remaining friable ACBM or friable suspected ACBM.

HOM. AREA	DESCRIPTION	SAMPLE DATE	ASBESTOS (Y/N/A)			FRIABLE	2022	RESPONSE	SPECIAL	TYPE	RECOMMENDATIONS
				DAM	QUANTITY		ASSESSMENT	ACTION	CLEANING	OF	
							40 CFR 763.88	START/END DATES	NEEDED	DAMAGE	REFER TO REPORT FOR DATES AND COST ESTIMATES
7	MASTIC FOR BLACK 12" X 12" VINYL FLOOR TILE										
	ROOM 14		A	N	55 SF	NF	5		N		GOOD CONDITION - O&M
	ROOM 13			N	55 SF	NF	5		N		GOOD CONDITION - O&M
	ROOM 12			N	55 SF	NF	5		N		GOOD CONDITION - O&M
	ROOM 10			N	55 SF	NF	5		N		GOOD CONDITION - O&M
	ROOM 5 UNDER OTHER FLOORING			N	55 SF	NF	5		N		GOOD CONDITION - O&M
8	BROWN 9" X 9" VINYL FLOOR TILE										
	ROOM 13		A	N	860 SF	NF	5		N		GOOD CONDITION - O&M
9	MASTIC FOR BROWN 9" X 9" VINYL FLOOR TILE										
	ROOM 13		A	N	860 SF	NF	5		N		GOOD CONDITION - O&M
10	GREY 9" X 9" VINYL FLOOR TILE										
	ROOM 15		A	N	1,000 SF	NF	5		N		GOOD CONDITION - O&M
11	MASTIC FOR GREY 9" X 9" VINYL FLOOR TILE										
	ROOM 15		A	N	1,000 SF	NF	5		N		GOOD CONDITION - O&M
12	TAN 9" X 9" VINYL FLOOR TILE										
	ROOM 5		A	N	912 SF	NF	5		N		GOOD CONDITION - O&M
13	MASTIC FOR TAN 9" X 9" VINYL FLOOR TILE										
	ROOM 5		A	N	912 SF	NF	5		N		GOOD CONDITION - O&M

ASBESTOS TYPE  
CHRY Chrysotile  
AMOS Amosite  
ACTI Actinolite  
ANTH Anthophyllite  
CROC Crocidolite  
NA/PS Not Analyzed/Positive Stop

QUANTITY  
SF Square Feet  
LF Linear Feet  
EA Each  
TO Total

TYPE OF MATERIAL  
M Miscellaneous  
S Surfacing  
T Thermal

ASBESTOS  
Y Yes  
N No  
A Assumed

NOTES  
HV - HEPA VACCUUM  
2X/WK - TWICE PER WEEK  
1X/WK - ONCE PER WEEK  
L - LOOSE  
DE - DETERRIORATED  
D - DAMAGED  
SD - SIGNIFICANT DAMAGE

- (1) Damaged or significantly damaged thermal system insulation ACM.
- (2) Damaged friable surfacing ACM.
- (3) Significantly damaged friable surfacing ACM.
- (4) Damaged or significantly damaged friable miscellaneous ACM.
- (5) ACBM with potential for damage.
- (6) ACBM with potential for significant damage.
- (7) Any remaining friable ACBM or friable suspected ACBM.

HOM. AREA	DESCRIPTION	SAMPLE DATE	ASBESTOS (Y/N/A)			FRIABLE	2022 ASSESSMENT 40 CFR 763.88	RESPONSE ACTION START/END DATES	SPECIAL CLEANING NEEDED	TYPE OF DAMAGE	
											RECOMMENDATIONS
				DAM	QUANTITY						REFER TO REPORT FOR DATES AND COST ESTIMATES
14	LIGHT GREY 12" X 12" VINYL FLOOR TILE										
	ROOM 12	12/28/22	N	N	1,000 SF						
15	MASTIC FOR LIGHT GREY 12" X 12" VINYL FLOOR TILE										
	ROOM 12	12/28/22	N	N	1,000 SF						
16	WHITE/GREEN 12" X 12" VINYL FLOOR TILE										
	NURSE	12/28/22	N	N	300 SF						
17	MASTIC FOR WHITE/GREEN 12" X 12" VINYL FLOOR TILE										
	NURSE	12/28/22	N	N	300 SF						
18	LIGHT GREY FLEX 12" X 12" VINYL FLOOR TILE										
	ROOM 16	12/28/22	N	N	1,000 SF						
19	MASTIC FOR LIGHT GREY FLEX 12" X 12" VINYL FLOOR TILE										
	ROOM 16	12/28/22	N	N	1,000 SF						
20	WHITE/GREY SPOTS 12" X 12" VINYL FLOOR TILE										
	HALLWAY TO CAFETERIA	12/28/22	N	N	600 SF						
	CAFETERIA			N	3,800 SF						

ASBESTOS TYPE  
CHRY Chrysotile  
AMOS Amosite  
ACTI Actinolite  
ANTH Anthophyllite  
CROC Crocidolite  
NA/PS Not Analyzed/Positive Stop

QUANTITY  
SF Square Feet  
LF Linear Feet  
EA Each  
TO Total

TYPE OF MATERIAL  
M Miscellaneous  
S Surfacing  
T Thermal

ASBESTOS  
Y Yes  
N No  
A Assumed

NOTES  
HV - HEPA VACCUUM  
2X/WK - TWICE PER WEEK  
1X/WK - ONCE PER WEEK  
L - LOOSE  
DE - DETERRIORATED  
D - DAMAGED  
SD - SIGNIFICANT DAMAGE

- (1) Damaged or significantly damaged thermal system insulation ACM.
- (2) Damaged friable surfacing ACM.
- (3) Significantly damaged friable surfacing ACM.
- (4) Damaged or significantly damaged friable miscellaneous ACM.
- (5) ACBM with potential for damage.
- (6) ACBM with potential for significant damage.
- (7) Any remaining friable ACBM or friable suspected ACBM.

HOM. AREA	DESCRIPTION	SAMPLE DATE	ASBESTOS (Y/N/A)			FRIABLE	2022	RESPONSE	SPECIAL	TYPE	RECOMMENDATIONS
				DAM	QUANTITY		ASSESSMENT	ACTION	CLEANING	OF	
							40 CFR 763.88	START/END DATES	NEEDED	DAMAGE	REFER TO REPORT FOR DATES AND COST ESTIMATES
21	MASTIC FOR WHITE/GREY SPOTS 12" X 12" VINYL FLOOR TILE										
	HALLWAY TO CAFETERIA	12/28/22	N	N	600 SF						
	CAFETERIA			N	3,800 SF						
22	DARK GREY 12" X 12" VINYL FLOOR TILE										
	CAFETERIA STORAGE	12/28/22	N	N	225 SF						
23	GREEN 9" X 9" VINYL FLOOR TILE										
	GYMNASIUM LOBBY STORAGE		A	N	60 SF	NF	5		N		GOOD CONDITION - O&M
24	MASTIC FOR GREEN 9" X 9" VINYL FLOOR TILE										
	GYMNASIUM LOBBY STORAGE		A	N	60 SF	NF	5		N		GOOD CONDITION - O&M
25	9" X 9" VINYL FLOOR TILE ASSUMED UNDER CARPET										
	STAFF KITCHEN		A	N		NF	5		N		GOOD CONDITION - O&M
	MAIN OFFICES			N		NF	5		N		GOOD CONDITION - O&M
	CONFERENCE ROOM			N		NF	5		N		GOOD CONDITION - O&M
	COUNCELING			N		NF	5		N		GOOD CONDITION - O&M
	CLASSROOM 9			N		NF	5		N		GOOD CONDITION - O&M
	CLASSROOM 11			N		NF	5		N		GOOD CONDITION - O&M
	GYMNASIUM LOBBY			N		NF	5		N		GOOD CONDITION - O&M
				TOTAL	4,500 SF						
26	SINK DAMPROOFING										
	CLASSROOMS		A	N	18 TO	NF	5		N		GOOD CONDITION - O&M
	STAFF KITCHEN			N	1 EA	NF	5		N		GOOD CONDITION - O&M

ASBESTOS TYPE  
 CHRY Chrysotile  
 AMOS Amosite  
 ACTI Actinolite  
 ANTH Anthophyllite  
 CROC Crocidolite  
 NA/PS Not Analyzed/Positive Stop

QUANTITY  
 SF Square Feet  
 LF Linear Feet  
 EA Each  
 TO Total

TYPE OF MATERIAL  
 M Miscellaneous  
 S Surfacing  
 T Thermal

ASBESTOS  
 Y Yes  
 N No  
 A Assumed

NOTES  
 HV - HEPA VACCUUM  
 2X/WK - TWICE PER WEEK  
 1X/WK - ONCE PER WEEK  
 L - LOOSE  
 DE - DETERRIORATED  
 D - DAMAGED  
 SD - SIGNIFICANT DAMAGE

- Damaged or significantly damaged thermal system insulation ACM.
- Damaged friable surfacing ACM.
- Significantly damaged friable surfacing ACM.
- Damaged or significantly damaged friable miscellaneous ACM.
- ACBM with potential for damage.
- ACBM with potential for significant damage.
- Any remaining friable ACBM or friable suspected ACBM.

HOM. AREA	DESCRIPTION	SAMPLE DATE	ASBESTOS (Y/N/A)			FRIABLE	2022	RESPONSE	SPECIAL	TYPE	RECOMMENDATIONS
				DAM	QUANTITY		ASSESSMENT	ACTION	CLEANING	OF	
							40 CFR 763.88	START/END DATES	NEEDED	DAMAGE	REFER TO REPORT FOR DATES AND COST ESTIMATES
27	MASTIC FOR 9" X 9" VINYL FLOOR TILE ASSUMED UNDER CARPET										
	STAFF KITCHEN		A	N		NF	5		N		GOOD CONDITION - O&M
	MAIN OFFICES			N		NF	5		N		GOOD CONDITION - O&M
	CONFERENCE ROOM			N		NF	5		N		GOOD CONDITION - O&M
	COUNCELING			N		NF	5		N		GOOD CONDITION - O&M
	CLASSROOM 9			N		NF	5		N		GOOD CONDITION - O&M
	CLASSROOM 11			N		NF	5		N		GOOD CONDITION - O&M
	GYMNASIUM LOBBY			N		NF	5		N		GOOD CONDITION - O&M
				TOTAL	4,500 SF						
28	INTERIOR WINDOW CAULKING										
	MAIN CORRIDORS		A	N		NF	5		N		GOOD CONDITION - O&M
	MAIN OFFICE			N		NF	5		N		GOOD CONDITION - O&M
	STAFF ROOM			N		NF	5		N		GOOD CONDITION - O&M
				TOTAL	100 TO						
29	INTERIOR DOOR CAULKING										
	MAIN CORRIDORS/CLASSROOM DOORS		A	N	25 TO	NF	5		N		GOOD CONDITION - O&M
30	YELLOW/BLUE TRIM 12" X 12" VINYL FLOOR TILE										
	ALL HALLWAYS AND CORRIDORS AT FIRST FLOOR	12/28/22	N	N	3,200 SF						
31	MASTIC FOR YELLOW/BLUE TRIM 12" X 12" VINYL FLOOR TILE										
	ALL HALLWAYS AND CORRIDORS AT FIRST FLOOR	12/28/22	N	N	3,200 SF						
32	TAN 12" X 12" VINYL FLOOR TILE										
	ROOM 10	12/28/22	N	N	900 SF						

ASBESTOS TYPE  
CHRY Chrysotile  
AMOS Amosite  
ACTI Actinolite  
ANTH Anthophyllite  
CROC Crocidolite  
NA/PS Not Analyzed/Positive Stop

QUANTITY  
SF Square Feet  
LF Linear Feet  
EA Each  
TO Total

TYPE OF MATERIAL  
M Miscellaneous  
S Surfacing  
T Thermal

ASBESTOS  
Y Yes  
N No  
A Assumed

NOTES  
HV - HEPA VACCUUM  
2X/WK - TWICE PER WEEK  
1X/WK - ONCE PER WEEK  
L - LOOSE  
DE - DETERRIORATED  
D - DAMAGED  
SD - SIGNIFICANT DAMAGE

- (1) Damaged or significantly damaged thermal system insulation ACM.
- (2) Damaged friable surfacing ACM.
- (3) Significantly damaged friable surfacing ACM.
- (4) Damaged or significantly damaged friable miscellaneous ACM.
- (5) ACBM with potential for damage.
- (6) ACBM with potential for significant damage.
- (7) Any remaining friable ACBM or friable suspected ACBM.

HOM. AREA	DESCRIPTION	SAMPLE DATE	ASBESTOS (Y/N/A)			FRIABLE	2022	RESPONSE	SPECIAL	TYPE	
				DAM	QUANTITY		ASSESSMENT 40 CFR 763.88	ACTION START/END DATES	CLEANING NEEDED	OF DAMAGE	RECOMMENDATIONS
											REFER TO REPORT FOR DATES AND COST ESTIMATES
33	ROUGH CEILING PLASTER										
	CLASSROOMS	7/6/2010	N	N							
	OFFICES			N							
	STORAGE ROOMS			N							
	BATHROOMS			N							
	BASEMENT			N							
	HALLWAY			N							
				TOTAL	25,000 SF						
34	MASTIC FOR TAN 12" X 12" VINYL FLOOR TILE										
	ROOM 10	12/28/22	N	N	900 SF						
35	1' X 1' ACOUSTICAL CEILING TILE										
	ROOM 1	1/28/2020	N	N	900 SF						
	ROOM 2			N	900 SF						
	ROOM 3			N	900 SF						
	ROOM 4			N	900 SF						
	ROOM 5			N	900 SF						
	ROOM 6			N	900 SF						
	TLC ROOM			N	900 SF						
	ROOM 7			N	900 SF						
	ROOM 8			N	900 SF						
	ROOM 10			N	1,000 SF						
	ROOM 11			N	1,000 SF						
	ROOM 12			N	1,000 SF						
	ROOM 13			N	1,000 SF						
	OFFICE/CONFERENCE ROOM			N	600 SF						
	NURSE			N	300 SF						
	ROOM 14			N	900 SF						
	ROOM 15			N	900 SF						
	ROOM 16			N	900 SF						
	ROOM 17			N	900 SF						
	STAGE			N	1,000 SF						
	GYMNASIUM			N	3,000 SF						
	MAIN HALLWAY			N	3,000 SF						

ASBESTOS TYPE  
CHRY Chrysotile  
AMOS Amosite  
ACTI Actinolite  
ANTH Anthophyllite  
CROC Crocidolite  
NA/PS Not Analyzed/Positive Stop

QUANTITY  
SF Square Feet  
LF Linear Feet  
EA Each  
TO Total

TYPE OF MATERIAL  
M Miscellaneous  
S Surfacing  
T Thermal

ASBESTOS  
Y Yes  
N No  
A Assumed

NOTES  
HV - HEPA VACCUUM  
2X/WK - TWICE PER WEEK  
1X/WK - ONCE PER WEEK  
L - LOOSE  
DE - DETERRIORATED  
D - DAMAGED  
SD - SIGNIFICANT DAMAGE

- (1) Damaged or significantly damaged thermal system insulation ACM.
- (2) Damaged friable surfacing ACM.
- (3) Significantly damaged friable surfacing ACM.
- (4) Damaged or significantly damaged friable miscellaneous ACM.
- (5) ACBM with potential for damage.
- (6) ACBM with potential for significant damage.
- (7) Any remaining friable ACBM or friable suspected ACBM.

HOM. AREA	DESCRIPTION	SAMPLE DATE	ASBESTOS (Y/N/A)			FRIABLE	2022	RESPONSE	SPECIAL	TYPE	RECOMMENDATIONS	
				DAM	QUANTITY		ASSESSMENT	ACTION	CLEANING	OF		
							40 CFR 763.88	START/END DATES	NEEDED	DAMAGE	REFER TO REPORT FOR DATES AND COST ESTIMATES	
36	2' X 4' SUSPENDED ACOUSTICAL CEILING TILE	1/28/2020	N									
	ROOM 9			N	900 SF							
	HALLWAY TO CAFETERIA			N	600 SF							
	CAFETERIA			N	3M800 SF							
37	DUCT INSULATION											
	KITCHEN		A	N	50 SF	NF	6		N		GOOD CONDITION - O&M	
	CAFETERIA ABOVE CEILING			N	50 SF	NF	5		N		GOOD CONDITION - O&M	
38	BEIGE 12" X 12" VINYL FLOOR TILE											
	ROOM 8		N/A	N	1,000 SF						NEW TILES. REFER TO MSDS.	
39	MASTIC FOR BEIGE 12" X 12" VINYL FLOOR TILE											
	ROOM 8		N/A	N	1,000 SF						NEW TILES. REFER TO MSDS.	
40	LIGHT BLUE 12" X 12" VINYL FLOOR TILE											
	ROOM 4		N/A	N	1,000 SF						NEW TILES. REFER TO MSDS.	
	ROOM 3			N	1,000 SF							
	ROOM 2			N	1,000 SF							
	ROOM 1			N	1,000 SF							
41	MASTIC FOR LIGHT BLUE 12" X 12" VINYL FLOOR TILE											
	ROOM 4		N/A	N	1,000 SF						NEW TILES. REFER TO MSDS.	
	ROOM 3			N	1,000 SF							
	ROOM 2			N	1,000 SF							
	ROOM 1			N	1,000 SF							

ASBESTOS TYPE  
CHRY Chrysotile  
AMOS Amosite  
ACTI Actinolite  
ANTH Anthophyllite  
CROC Crocidolite  
NA/PS Not Analyzed/Positive Stop

QUANTITY  
SF Square Feet  
LF Linear Feet  
EA Each  
TO Total

TYPE OF MATERIAL  
M Miscellaneous  
S Surfacing  
T Thermal

ASBESTOS  
Y Yes  
N No  
A Assumed

NOTES  
HV - HEPA VACCUUM  
2X/WK - TWICE PER WEEK  
1X/WK - ONCE PER WEEK  
L - LOOSE  
DE - DETERRIORATED  
D - DAMAGED  
SD - SIGNIFICANT DAMAGE

- (1) Damaged or significantly damaged thermal system insulation ACM.
- (2) Damaged friable surfacing ACM.
- (3) Significantly damaged friable surfacing ACM.
- (4) Damaged or significantly damaged friable miscellaneous ACM.
- (5) ACBM with potential for damage.
- (6) ACBM with potential for significant damage.
- (7) Any remaining friable ACBM or friable suspected ACBM.